


1/20

*FIG. 1*

2/20





FIG. 2

3/20

*FIG. 3*

4/20




FIG. 4

5/20




FIG. 5

6/20




FIG. 6

7/20




FIG. 7

8/20




FIG. 8




FIG. 9

9/20




FIG. 10




FIG. 11

10/20




FIG. 12






FIG. 13

11/20

*FIG. 14**FIG. 15*

12/20




FIG. 16




FIG. 17

13/20





FIG. 18

14/20

*FIG. 19*




FIG. 20

16/20





FIG. 21

Extension Force
Outside of Cup (↕)

17/20

Sample A DSC Test Result: Laboratory Testing Request 29016



18/20




FIG. 23

19/20




FIG. 24

20/20




FIG. 25