

## Machining of an Article

### Abstract

A method of forming a profile of a leading edge on an aerofoil having a leading edge extending along an axis and providing a fluid jet that has a Gaussian energy distribution  
5 profile. The jet is traversed along a path that substantially follows the axis, the maximum energy of the fluid jet being directed to a location offset from the axis.

Fig. 4