




FIG. 1

2/10




FIG. 2

3/10




FIG. 3

		Column Output Signals	
		$+V_{bias}$	$-V_{bias}$
Row Output Signals	0	Stable	Stable
	$+\Delta V$	Relax	Actuate
	$-\Delta V$	Actuate	Relax

FIG. 4

4/10




FIG. 5A




FIG. 5B

5/10




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7




FIG. 8A




FIG. 8B

8/10



FIG. 9A




FIG. 9B




FIG. 9C




FIG. 10




FIG. 11

10/10




FIG. 12A




FIG. 12B