

FIG.1


H spreading zone
Embrittlement zone
+31
+25
+19
+16
+13
+7
Cleaving plane
H peak
500
1500
2500
3500
4500
X


+13
ΔE (in keV)
He peak
He spreading zone