




FIG. 1A





FIG. 1B

2/8

**FIG. 2**




FIG. 3A




FIG. 3B







FIG. 3C

4/8

**FIG. 4****FIG. 5**

5/8

**FIG. 6**

6/8




FIG 7A



SPUTTERING STATION 1									
MgO-TiO									
STEP 1			STEP 2				STEP 3		
Ar	N ₂	DUR	Ar	N ₂	POWER	DUR	Ar	N ₂	DUR
24 SCCM	16 SCCM	2 SEC	24 SCCM	16 SCCM	0.5 kW	16 SEC	5 SCCM	0 SCCM	1 SEC

FIG 7B



SPUTTERING STATION 2									
MgO-TiO									
STEP 1			STEP 2				STEP 3		
Ar	N ₂	DUR	Ar	N ₂	POWER	DUR	Ar	N ₂	DUR
150 SCCM	10 SCCM	1 SEC	150 SCCM	10 SCCM	0.6 kW	8.5 SEC	5 SCCM	0 SCCM	1 SEC

FIG 7C

7/8

**FIG 8A****FIG 8B**

8/8

**FIG 9A****FIG 9B**