

FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 5A




FIG. 5B




FIG. 6A




FIG. 6B




FIG. 6C




FIG. 7A




FIG. 7B




FIG. 7C




Figure 1 is a schematic diagram of a mechanical assembly. It shows a horizontal shaft (114) passing through a complex, curved, and twisted component (115). A coordinate system is shown on the right with the X-axis pointing left and the Z-axis pointing up.

FIG. 9




FIG. 10A




FIG. 10B




FIG. 10C




FIG. 11

