

FIG.1




FIG.2




FIG.3

<WITHOUT REFLECTOR IN CHAMFERED HOLLOW PART>




FIG.4

<WITH REFLECTOR IN CHAMFERED HOLLOW PART>





FIG.5

(1)

<WITHOUT REFLECTOR IN CHAMFERED HOLLOW PART>
 <30 MINUTES AFTER START OF HEATING>



(2)

<WITHOUT REFLECTOR IN CHAMFERED HOLLOW PART>
 <60 MINUTES AFTER START OF HEATING>





FIG.6

(1)

<WITH REFLECTOR IN CHAMFERED HOLLOW PART>
 <30 MINUTES AFTER START OF HEATING>



(2)

<WITH REFLECTOR IN CHAMFERED HOLLOW PART>
 <60 MINUTES AFTER START OF HEATING>




FIG.7

