

FIG.1




FIG.2




FIG.3




FIG.4




FIG.5




FIG.6





Combination	Arrangement of marking	Outputs of sensors
1	 Blank Blank	
2	 Blank M	
3	 M Blank	
4	 M M	

FIG.7





FIG.8




FIG.9

