

REPAIR OF A COATING ON A TURBINE COMPONENT

ABSTRACT :

A method is provided for repairing an area of damaged coating on a component of a turbine module in a gas turbine engine, the component formed of a base material having a diffusion coating applied to the base material. The repair may be accomplished in place by directly heating the area to which a touch-up coating material has been applied with a hot gas plasma without the need to place the component in an oven for curing and heat treatment of the touch-up coating applied to the damaged area.

Fig. 5