




FIG.1




FIG.2

Area	Trap No.	Trap Type	Model	Manufacture	Application	Pressure	Priority	Result	---
001	0001	BUCKET	ABC	STU	Heating	0-50	Important	Good	---
001	0002	THERMO	CDE	XYZ	Heating	0-50	Important	Good	---
001	0003	TEMP.ADJ.	EFG	STU	Heating	0-50	Important	Good	---
001	0004	TEMP.ADJ.	GHI	STU	Heating	0-50	Important	Good	---
001	0005	FLOAT	JKL	XYZ	Heating	0-50	Important	Good	---
001	0006	TEMP.ADJ.	GHI	STU	Heating	0-50	Important	Good	---
001	0007	TEMP.ADJ.	EFG	STU	Heating	0-50	General	Good	---
001	0008	THERMO	CDE	XYZ	Heating	0-50	General	Good	---
001	0009	THERMO	CDE	XYZ	Heating	0-50	General	Good	---
001	0010	TEMP.ADJ.	GHI	STU	Heating	0-50	General	Good	---
001	0011	THERMO	CDE	XYZ	Heating	0-50	General	Good	---
001	0012	DISC	LMN	STU	Drip	50-150	Important	Not Checked Yet	---
001	0013	THERMO	CDE	XYZ	Drip	50-150	Important	Not Checked Yet	---
001	0014	DISC	LMN	STU	Drip	50-150	Important	Not Checked Yet	---
001	0015	DISC	LMN	STU	Drip	50-150	Important	Not Checked Yet	---
---	---	---	---	---	---	---	---	---	---

FIG.3

4/18




FIG.4




FIG.5

6/18




FIG.6

7/18




FIG. 7

8/18




FIG.8

9/18




FIG.9

10/18




FIG.10

11/18




FIG.11

12/18





FIG. 12A

13/18



14/18




FIG.13




FIG.14




FIG. 15A

17/18




FIG.15B

18/18




FIG.16