

FIG. 1





FIG. 2

FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B











FIG. 5A**FIG. 5B****FIG. 5C**

FIG. 6**FIG. 7**






FIG. 10A




FIG. 10B

FIG. 11




FIG. 12





FIG. 13

FIG. 14

INTERNAL PRESSURE				INTERNAL PRESSURE				INTERNAL PRESSURE			
P_{a1}	P_{b1}	P_{c1}		P_{a2}	P_{b2}	P_{c2}		P_{a_l}	P_{b_l}	P_{c_l}	
COORDINATE	THREE-DIMENSIONAL SHAPE			COORDINATE	THREE-DIMENSIONAL SHAPE			COORDINATE	THREE-DIMENSIONAL SHAPE		
	X_{11}	Y_{11}	Z_{11}		X_{12}	Y_{12}	Z_{12}		X_{1l}	Y_{1l}	Z_{1l}
	X_{21}	Y_{21}	Z_{21}		X_{22}	Y_{22}	Z_{22}		X_{2l}	Y_{2l}	Z_{2l}
	$\cdot$	$\cdot$	$\cdot$		$\cdot$	$\cdot$	$\cdot$		$\cdot$	$\cdot$	$\cdot$
	$\cdot$	$\cdot$	$\cdot$		$\cdot$	$\cdot$	$\cdot$		$\cdot$	$\cdot$	$\cdot$
X_{n1}	Y_{n1}	Z_{n1}		X_{n2}	Y_{n2}	Z_{n2}		X_{nl}	Y_{nl}	Z_{nl}	
CL1				CL2				CL3			

FIG. 15




FIG. 16