

Abstract

Disposal Method for Entirely Recycling Solid Refuse

A disposal method for entirely recycling solid refuse includes the following steps:

5 sorting, crushing, drying, pressing with high pressure to shaped articles, producing charcoal from combustible refuse in high temperature and firing incombustible refuse in high temperature, at last cooling high temperature articles to obtain solid fuel with various shapes and bricks or board used for building. The method achieves entirely recycling house refuse, especial solid refuse. The method recycles solid refuse to

10 obtain fuel and building material with economic value. The method is simple and its processing cost is low.

[No Figure]