

FIG.1





FIG.2

(A)



(B)






FIG.3

(A)




$$\theta 1=0^{\circ}, \theta 2=0^{\circ}$$

(B)




$$\theta 1=10.00^{\circ}, \theta 2=20.00^{\circ}$$

(C)




$$\theta 1=15.00^{\circ}, \theta 2=23.86^{\circ}$$

(D)




$$\theta 1=18.00^{\circ}, \theta 2=25.46^{\circ}$$

(E)



$$\theta 1=24.00^{\circ}, \theta 2=27.94^{\circ}$$


(F)



$$\theta 1=30.00^{\circ}, \theta 2=30.00^{\circ}$$


FIG.4

(A)




$$\theta 1=0^\circ, \theta 2=0^\circ$$

(B)




$$\theta 1=10.53^\circ, \theta 2=6.00^\circ$$

(C)




$$\theta 1=13.97^\circ, \theta 2=9.00^\circ$$

(D)




$$\theta 1=18.53^\circ, \theta 2=15.00^\circ$$

(E)



$$\theta 1=20.23^\circ, \theta 2=18.00^\circ$$

(F)



$$\theta 1=22.50^\circ, \theta 2=22.50^\circ$$