

1 / 9




FIG. 1




FIG. 2

3 / 9




FIG. 3




FIG. 4

4 / 9




FIG. 5




FIG. 6

5 / 9




FIG. 7




FIG. 8

6 / 9




FIG. 9




FIG. 10





FIG. 11

8 / 9



- B sintered @ 1300 $^{\circ}\text{C}$, 1wt.% NaOH + 25wt.% NaBH₄ solution
- C sintered @ 1300 $^{\circ}\text{C}$, 5wt.% NaOH + 25wt.% NaBH₄ solution
- D sintered @ 1300 $^{\circ}\text{C}$, 10wt.% NaOH + 25wt.% NaBH₄ solution
- F sintered @ 1200 $^{\circ}\text{C}$, 1wt.% NaOH + 25wt.% NaBH₄ solution
- G sintered @ 1200 $^{\circ}\text{C}$, 5wt.% NaOH + 25wt.% NaBH₄ solution
- H sintered @ 1200 $^{\circ}\text{C}$, 10wt.% NaOH + 25wt.% NaBH₄ solution
- J sintered @ 1100 $^{\circ}\text{C}$, 1wt.% NaOH + 25wt.% NaBH₄ solution
- E sintered @ 1100 $^{\circ}\text{C}$, 5wt.% NaOH + 25wt.% NaBH₄ solution
- L sintered @ 1100 $^{\circ}\text{C}$, 10wt.% NaOH + 25wt.% NaBH₄ solution

FIG. 12

9 / 9




FIG. 13




FIG. 14