




1/10

**FIGURE 1**


2/10

**FIGURE 2**

3/10

**FIGURE 3**


4/10




- 1) Heat from 60.00 °C to 135.00 °C at 10.00 °C/min 3) Hold for 8.0 min at -50.00 °C
2) Cool from 135.00 °C to -50.00 °C at 10.00 °C/min 4) Heat from -50.00 °C to 210.00 °C at 10.00 °C/min

FIGURE 4


5/10

**FIGURE 5**

6/10

**FIGURE 6**

7/10

**FIGURE 7**






FIGURE 8

9/10

**FIGURE 9**

10/10

**FIGURE 10**