

1/6

FIG. 1




FIG. 3




FIG. 2A
FORMING
ADHESIVE
FILMS




FIG. 2B
LOCATING
BALLS




FIG. 2C
APPLYING
PRESSURE




FIG. 2D
REMOVING
MASK




FIG. 2E
APPLYING
FLUX




FIG. 2F
REFLOW
(N₂ FURNACE)




FIG. 2G

RINSING



FIG. 4A





FIG. 4B



4/6

FIG. 5A





FIG. 5B



5/6

FIG. 6A





FIG. 6B



6/6

FIG. 7A




FIG. 7B




FIG. 7C




FIG. 7D

