CHEMICAL-MECHANICAL PLANARIZATION OF COPPER METALLURGY

ABSTRACT

Copper or a copper alloy is removed by chemical-mechanical planarization (CMP) in a slurry of an oxidizer, an oxidation inhibitor, and an additive that appreciably regulates copper complexing with the oxidation inhibitor.

FIG.1