

DRAWINGS




FIG. 1




FIG. 2



FIG. 3A




FIG. 3B




FIG. 3C

	0	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16
0	3	-1	0	0	-1	0	0	-1	0	0	0	0	0	0	0	0	0
1	-1	2	-1	0	0	0	0	0	0	0	0	0	0	0	0	0	0
2	0	-1	2	-1	0	0	0	0	0	0	0	0	0	0	0	0	0
3	0	0	-1	1	0	0	0	0	0	0	0	0	0	0	0	0	0
4	-1	0	0	0	2	-1	0	0	0	0	0	0	0	0	0	0	0
5	0	0	0	0	-1	2	-1	0	0	0	0	0	0	0	0	0	0
6	0	0	0	0	0	-1	1	0	0	0	0	0	0	0	0	0	0
7	-1	0	0	0	0	0	0	2	-1	0	0	0	0	0	0	0	0
8	0	0	0	0	0	0	0	-1	4	-1	0	-1	0	0	-1	0	0
9	0	0	0	0	0	0	0	0	-1	2	-1	0	0	0	0	0	0
10	0	0	0	0	0	0	0	0	0	-1	1	0	0	0	0	0	0
11	0	0	0	0	0	0	0	0	-1	0	0	2	-1	0	0	0	0
12	0	0	0	0	0	0	0	0	0	0	0	-1	2	-1	0	0	0
13	0	0	0	0	0	0	0	0	0	0	0	0	-1	1	0	0	0
14	0	0	0	0	0	0	0	0	-1	0	0	0	0	0	2	-1	0
15	0	0	0	0	0	0	0	0	0	0	0	0	0	0	-1	2	-1
16	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0	-1	1

FIG. 3D




FIG. 3E




FIG. 3F




FIG. 4




FIG. 5