




Fig. 1




Fig. 2





Fig. 3






Fig. 5




Fig. 6




Fig. 7




Fig. 8




Fig. 9





Fig. 10

**Fig. 11**




Fig. 12




Fig. 13




Fig. 14




Fig. 15




Fig. 16




Fig. 17




Fig. 18




Fig. 19




Fig. 20a

Fig. 20b




Fig. 21a

Fig. 21b




Fig. 22a

Fig. 22b




Fig. 23




Fig. 24





Fig. 25






Fig. 27




Fig. 28




Fig. 29





Fig. 30

**Fig. 31**




Fig. 32




Fig. 33




Fig. 34




Fig. 35




Fig. 36




Fig. 37




Fig. 38a




Fig. 38b

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11	T12
U1	0	0	0	0	$C_{1,5}$	$C_{1,6}$	$C_{1,7}$	$C_{1,8}$	$C_{1,9}$	$C_{1,10}$	0	0
U2	0	0	0	0	$C_{2,5}$	$C_{2,6}$	$C_{2,7}$	0	0	0	0	0
U3	0	0	0	0	0	0	0	0	$C_{3,9}$	$C_{3,10}$	$C_{3,11}$	$C_{3,12}$
U4	0	0	0	0	0	0	$C_{4,7}$	$C_{4,8}$	$C_{4,9}$	$C_{4,10}$	0	0
U5	0	$C_{5,2}$	$C_{5,3}$	0	$C_{5,5}$	$C_{5,6}$	0	0	0	0	0	0
U6	0	0	0	$C_{6,4}$	0	0	0	$C_{6,8}$	$C_{6,9}$	0	0	$C_{6,12}$
U7	$C_{7,1}$	$C_{7,2}$	0	$C_{7,4}$	$C_{7,5}$	0	0	0	0	0	0	0
U8	$C_{8,1}$	$C_{8,2}$	$C_{8,3}$	$C_{8,4}$	0	0	0	0	0	0	0	0

Fig. 39

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11	T12
U1	0	0	0	0	$C_{1,5}$	$C_{1,6}$	$C_{1,7}$	$C_{1,8}$	$C_{1,9}$	$C_{1,10}$	0	0
U2	0	0	0	0	$C_{2,5}$	$C_{2,6}$	$C_{2,7}$	0	0	0	0	0
U3	0	0	0	0	0	0	0	0	$C_{3,9}$	$C_{3,10}$	$C_{3,11}$	$C_{3,12}$
U4	0	0	0	0	0	0	$C_{4,7}$	$C_{4,8}$	$C_{4,9}$	$C_{4,10}$	0	0
U5	0	$C_{5,2}$	$C_{5,3}$	0	$C_{5,5}$	$C_{5,6}$	0	0	0	0	0	0
U6	0	0	0	$C_{6,4}$	0	0	0	$C_{6,8}$	$C_{6,9}$	0	0	$C_{6,12}$
U7	$C_{7,1}$	$C_{7,2}$	0	$C_{7,4}$	$C_{7,5}$	0	0	0	0	0	0	0
U8	$C_{8,1}$	$C_{8,2}$	$C_{8,3}$	$C_{8,4}$	0	0	0	0	0	0	0	0

Fig. 40

	T1	T2	T3	T4	T5	T6	T7	T8	T9	T10	T11	T12
U1	0	0	0	0	C _{1,5}	C _{1,6}	C _{1,7}	C _{1,8}	C _{1,9}	C _{1,10}	0	0
U2	0	0	0	0	C _{2,5}	C _{2,6}	C _{2,7}	0	0	0	0	0
U3	0	0	0	0	0	0	0	0	C _{3,9}	C _{3,10}	C _{3,11}	C _{3,12}
U4	0	0	0	0	0	0	C _{4,7}	C _{4,8}	C _{4,9}	C _{4,10}	0	0
U5	0	C _{5,2}	C _{5,3}	0	C _{5,5}	C _{5,6}	0	0	0	0	0	0
U6	0	0	0	C _{6,4}	0	0	0	C _{6,8}	C _{6,9}	0	0	C _{6,12}
U7	C _{7,1}	C _{7,2}	0	C _{7,4}	C _{7,5}	0	0	0	0	0	0	0
U8	C _{8,1}	C _{8,2}	C _{8,3}	C _{8,4}	0	0	0	0	0	0	0	0

Fig. 41

