




Figure 1




Figure 2

3/20




Figure 3




Figure 4




Figure 5

4/20




Figure 6




Figure 7




Figure 8A




Figure 8B





Figure 8C



- Ⓐ - Material from 0.3 to 0.4 mm
- Ⓑ - Pressing depth from 25 to 30 mm
- Ⓒ - Beams closer together

Figure 8D

6/20




Figure 8E

7/20




Figure 9A




Figure 9B




Figure 9C




Figure 9D




Figure 9E




Figure 9F




Figure 9G




Figure 9H

8/20




Figure 10




Figure 11




Figure 12




Figure 13




Figure 14A

12/20




Figure 14B

13/20




Figure 15

14/20




Figure 16




Figure 17




Figure 18

16/20




Figure 19

17/20




Figure 20

18/20




Figure 21

19/20




Figure 22




Figure 23




Figure 24