







100
FIGURE 1

FIGURE 2








400
FIGURE 4

5/11



400
FIGURE 5

600

610	620	630	640
Vehicle Signal ID	Signal Type	Timestamp	Location
11xb2a	Manual control takeover	05:12:2017::13:36:58	05_87_322
05dp4w	Request for remote assistance	06:22:2017::05:23:32	48_23_102
47fgu1e	Extended wait	02:19:2017::00:07:44	51_309_04
89fc3q	Unprotected turn	04:01:2017::18:44:25	38_12_89
00lk5m	Occluded sensor view	09:23:2017::19:25:49	43_155_53
62vb2s	Rapid brake application	10:17:2017::08:57:12	37_64_202
59em6a	Limited sensor view	09:30:2017::11:37:05	57_24_33
78ee4d	Unprotected lane crossing	10:25:2017::15:09:39	39_88_297

FIGURE 6

7/11


700

FIGURE 7





FIGURE 8



SUBSTITUTE SHEET (RULE 26)

FIGURE 9




FIGURE 10

Segment	Route 810	Route 820	Route 830
a	1	1	1
b	1	1	1
c	9	5	5
d	1	5	1
e	1	5	1
f	5	1	1
g	1	0	1
h	1	0	0
Total:	20	18	11

FIGURE 11