

Continuous injection of gaseous defoamer
RAW-MATERIAL
Load the vessel with a leucoindigo salt solution containing aromatic amines
Start heating for evaporation of water and aromatic amines
Evaporation of water with aromatic amines
FINAL PRODUCT
Purified leucoindigo salt solution having undetectable amounts of aromatic amines
Continuous replacement of the water, in liquid and/or gaseous form

Figure 1



Continuous injection of gaseous defoamer
RAW-MATERIAL
Load the vessel with a leucoindigo salt solution containing aromatic amines
Start heating for evaporation of water and aromatic amines
Evaporation of water with aromatic amines
FINAL PRODUCT
Purified leucoindigo salt solution having undetectable amounts of aromatic amines
Continuous replacement of the water, in liquid and/or gaseous form

Figure 1