






FIG.1

THERE IS DOUBT OF
FRAUD OR FAULTY
GAME TOKEN COIN



TOTAL NUMBER OF READS USING CAMERA	0	4	1	2	4
TOTAL NUMBER OF READS USING RFID	0	4	2	2	3
SITTING NUMBER	6	5	3	2	1



THERE IS DOUBT OF FAULTY READ BY
CAMERA DUE TO BLIND SPOT ETC.

FIG.2




FIG.3

READ RESULTS OF CHIPS IN BET AREA

PLACE AND ID OF BET CHIPS	ONE FOR BANKER (ID3)	TWO FOR BANKER (ID12 AND ID13) TWO FOR BANKER PAIR (ID6 AND ID18)	TWO FOR PLAYER (ID29 AND ID54)	ONE FOR BANKER PAIR (ID75) ONE FOR PLAYER PAIR (ID77)	ONE FOR BANKER (ID97) ONE FOR PLAYER PAIR (ID68)
READ RESULT USING CAMERA	ONE FOR BANKER	TWO FOR BANKER	TWO FOR PLAYER	NOT AVAILABLE	ONE FOR BANKER ONE FOR PLAYER PAIR
READ RESULT USING RFID (READ ID)	ID3	ID6, 12, 13, 18	ID29, 54	NOT AVAILABLE	ID68, 97
SITTING NUMBER	6	5	3	2	1

GAME RESULT DETERMINED BY GAME RESULT DETERMINATION DEVICE	BANKER WINS
ID DETERMINED BY CHIP TRAY DETERMINATION DEVICE AS CHIPS ARE INCREASED BEFORE AND AFTER COLLECTION	ID6, 18, 29, 54, 68, 75, 77

FIG.4




FIG.5




FIG.6A




FIG.6B




FIG. 7

MISMATCH WITH AMOUNT OF
MONEY THAT HAS TO BE PAID
(DOUBT OF ERROR)

THERE IS DOUBT OF
FRAUD OR FAULTY
GAME TOKEN COIN

TOTAL NUMBER OF CHIPS THAT HAVE TO BE PAID	0	0	2	0	4
TOTAL NUMBER OF READS USING CAMERA	0	0	2	0	3
TOTAL NUMBER OF READS USING RFID	0	0	1	0	3
SITTING NUMBER	CONFIRMATION AREA FOR 6	CONFIRMATION AREA FOR 5	CONFIRMATION AREA FOR 3	CONFIRMATION AREA FOR 2	CONFIRMATION AREA FOR 1

FIG.8




FIG. 9




FIG.10




FIG. 11




FIG.12




FIG.13




FIG.14