




Figure 1




Figure 1b





Figure 2






Figure 4




Figure 5a(i)




Figure 5a(ii)




Figure 5a(iii)




Figure 5a(iv)




Figure 5a(v)




Figure 5a(vi)




Figure 5a(vii)




Figure 5b(i)




Figure 5b(ii)




Figure 5b(iii)




Figure 5b(iv)




Figure 5b(v)




Figure 5b(vi)





Figure 5b(vii)


Figure 5



Pump Unit fully seated and engaged to the motor.

Figure 6a

Figure 6



Pump Unit slides out. Unit slides easily in and out. No fastening required.

Figure 6b







Figure 7






Figure 8