




FIG.1




FIG. 2




FIG.3




FIG.4

FIG.5




FIG.6




FIG.7A




FIG.7B

17  
↙

| ID NUMBER     | CASINO NAME | TYPE                 | FACE VALUE | LOCATION INFORMATION HISTORY |
|---------------|-------------|----------------------|------------|------------------------------|
| ⋮             | ⋮           | ⋮                    | ⋮          | ⋮                            |
| apxx7216-3319 | ABC Casino  | ROLLING CHIP FOR VIP | \$500      | ○→○→...→○→○                  |
| apxx7216-3320 | ABC Casino  | ROLLING CHIP FOR VIP | \$1,000    | ○→○→...→○→○                  |
| apxx7216-3321 | ABC Casino  | ROLLING CHIP FOR VIP | \$1,000    | ○→○→...→○→○                  |
| ⋮             | ⋮           | ⋮                    | ⋮          | ⋮                            |

FIG.8





FIG. 9

GAME TOKEN POSSIBLY  
WRONG OR DEFECTIVE



|                                |   |   |   |   |   |
|--------------------------------|---|---|---|---|---|
| TOTAL NUMBER<br>READ BY CAMERA | 0 | 4 | 1 | 2 | 4 |
| TOTAL NUMBER<br>READ BY RFID   | 0 | 4 | 2 | 2 | 3 |
| SITTING NUMBER                 | 6 | 5 | 3 | 2 | 1 |

POSSIBILITY OF  
READ ERROR OF CAMERA DUE  
TO BLIND SPOT OR THE LIKE




FIG.10




FIG.11

CHIP READING RESULT AT BETTING AREA

|                                     |                                 |                                                                                          |                                          |                                                                                |                                                                           |
|-------------------------------------|---------------------------------|------------------------------------------------------------------------------------------|------------------------------------------|--------------------------------------------------------------------------------|---------------------------------------------------------------------------|
| PLACE AND ID OF<br>BET CHIP         | ONE PIECE ON<br>BANKER<br>(ID3) | TWO PIECES ON<br>BANKER<br>(ID12 AND 13)<br>TWO PIECES ON<br>BANKER PAIR<br>(ID6 AND 18) | TWO PIECES ON<br>PLAYER<br>(ID29 AND 54) | ONE PIECE ON<br>BANKER PAIR<br>(ID75)<br>ONE PIECE ON<br>PLAYER PAIR<br>(ID77) | ONE PIECE ON<br>BANKER<br>(ID97)<br>ONE PIECE ON<br>PLAYER PAIR<br>(ID68) |
| READING RESULT<br>BY CAMERA         | ONE PIECE ON<br>BANKER          | TWO PIECE ON<br>BANKER                                                                   | TWO PIECES ON<br>PLAYER                  | NONE                                                                           | ONE PIECE ON<br>BANKER<br>ONE PIECE ON<br>PLAYER PAIR                     |
| READING RESULT<br>BY RFID (READ ID) | ID3                             | ID6, 12, 13, 18                                                                          | ID29, 54                                 | NONE                                                                           | ID68, 97                                                                  |
| SITTING<br>NUMBER                   | 6                               | 5                                                                                        | 3                                        | 2                                                                              | 1                                                                         |

|                                                                                                                    |                             |
|--------------------------------------------------------------------------------------------------------------------|-----------------------------|
| GAME RESULT DETERMINED BY<br>GAME RESULT<br>DETERMINATION DEVICE                                                   | BANKER WINS                 |
| ID THAT CHIP TRAY DETERMINATION DEVICE<br>DETERMINES BEING INCREASED FROM<br>BEFORE COLLECTION TO AFTER COLLECTION | ID6, 18, 29, 54, 68, 75, 77 |

FIG.12




FIG.13




FIG.14A




FIG.14B




FIG.15

|                                     |                           |                           |                           |                           |                           |
|-------------------------------------|---------------------------|---------------------------|---------------------------|---------------------------|---------------------------|
| TOTAL NUMBER<br>EXPECTED TO BE PAID | 0                         | 0                         | 2                         | 0                         | 4                         |
| TOTAL NUMBER<br>READ BY CAMERA      | 0                         | 0                         | 2                         | 0                         | 3                         |
| TOTAL NUMBER<br>READ BY RFID        | 0                         | 0                         | 1                         | 0                         | 3                         |
| SITTING NUMBER                      | CONFIRMATION<br>AREA OF 6 | CONFIRMATION<br>AREA OF 5 | CONFIRMATION<br>AREA OF 3 | CONFIRMATION<br>AREA OF 2 | CONFIRMATION<br>AREA OF 1 |

GAME TOKEN POSSIBLY  
WRONG OR DEFECTIVE

DISAGREES WITH AMOUNT  
EXPECTED TO BE PAID  
(POSSIBILITY OF ERROR)

FIG.16




FIG.17




FIG.18




FIG. 19




FIG. 20






FIG.22




FIG.23




FIG.24




FIG.25




FIG.26




FIG.27




FIG.28




FIG.29




FIG.30




FIG.31




FIG.32

FIG.33







FIG.35




FIG.36





FIG.37




FIG.38




FIG.39




FIG.40




FIG.41




FIG. 42




FIG.43




FIG.44




FIG.45





FIG. 46



42b





FIG.47




FIG.48




FIG.49




FIG.50




FIG.51A




FIG.51B




FIG. 52




FIG. 53




FIG.54




FIG.55




FIG.56




FIG.57




FIG.58