

**MODIFICATION AND REPAIR OF FILM COOLING
HOLES IN GAS TURBINE ENGINE COMPONENTS**

ABSTRACT OF THE DISCLOSURE

- 5 A method for modifying cooling holes in a gas turbine engine film-cooled component by machining cooling hole outlets to enlarge the outlets and remove any portion of the cooling hole walls which might exhibit cracks.

Figure 4