




FIG. 1A




FIG. 1B




FIG. 1C




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7A




FIG. 7B

5/48




FIG. 8




FIG. 9




FIG. 10




FIG. 10A




FIG. 11A




FIG. 11B




FIG. 12

FIG. 12A

FIG. 12B




FIG. 13A




FIG. 13B




FIG. 14




FIG. 15A




FIG. 15B




FIG. 15C




FIG. 15D




FIG. 16




FIG. 17




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25A




FIG. 25B




FIG. 26





FIG. 27






FIG. 32




FIG. 33




FIG. 34




FIG. 35




FIG. 36




FIG. 37




FIG. 38




FIG. 39




FIG. 40




FIG. 41




FIG. 42




FIG. 43




FIG. 44




FIG. 45




FIG. 46




FIG. 47




FIG. 48




FIG. 49




FIG. 50




FIG. 51




FIG. 52




FIG. 53




FIG. 54




FIG. 55




FIG. 56




FIG. 57




FIG. 58




FIG. 59

27/48




FIG. 60




FIG. 61




FIG. 62




FIG. 63




FIG. 64




FIG. 65




FIG. 66

31/48




FIG. 67




FIG. 68




FIG. 69




FIG. 70




FIG. 71

33/48




FIG. 72




FIG. 73




FIG. 74




FIG. 75A




FIG. 75B




FIG. 76




FIG. 77




FIG. 78




FIG. 79




FIG. 80




FIG. 81




FIG. 82




FIG. 83




FIG. 84




FIG. 85





FIG. 86


41/48

FIG. 87



42/48

FIG. 88



43/48

FIG. 89

1400

1402


Enter Native Annulus Area

_____ mm²

The diagram shows a large rectangular frame labeled 1400. Inside the frame, there is a smaller rectangular box labeled 1402. This box contains the text 'Enter Native Annulus Area' followed by a blank line and the unit 'mm²'.

44/48

FIG. 90



45/48


FIG. 91

1500

1502


Enter Native Annulus Area
_____ mm²

FIG. 92



47/48

FIG. 93



48/48

FIG. 94

