

Figure 1: Examples of Woven Fabrics (Scrim)




Figure 2: Sample preparation for weld testing




Figure 3: Cutting stripes for weld testing




Figure 4: Testing of weld quality: tear with pliers until sample failure




Figure 5: Sample failure inside the weld seam ("peal in the seam").




Figure 6: Schematic of Multi-Layer Structure

