


Fig. 1



X-axis: Shear rate γ [1/s]
Left Y-axis: Viscosity η [Pa·s]
Right Y-axis: Shear stress τ [Pa]

Fig. 2








Fig. 3

Fig. 4**A**


F1 = F12; F2 = F13; F3 = F14; F4 = F15

B

F1 = F12; F2 = F13; F3 = F14; F4 = F15

Fig. 5**A**


F1 = F12; F2 = F13; F3= F14; F4 = F15

B

F1 = F12; F2 = F13; F3= F14; F4 = F15

Fig. 5 continued


C



F1 = F12; F2 = F13; F3= F14; F4 = F15


Fig. 6

A




F1 = F12; F2 = F13; F3= F14; F4 = F15

B




F1 = F12; F2 = F13; F3= F14; F4 = F15

Fig. 6 continued




F1 = F12; F2 = F13; F3 = F14; F4 = F15




F1 = F12; F2 = F13; F3 = F14; F4 = F15

Fig. 7




F1 = F12; F2 = F13; F3 = F14; F4 = F15

Fig. 8




F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21

Fig. 9



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21


Fig. 10



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21


Fig. 11

A



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21


B



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21


Fig. 12

A



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21


B



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21

Fig. 12 continued


C



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21

Fig. 13

A



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21

B

F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21






Fig. 13 continued

C




F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21

D



F1 = F13; F2 = F16; F3 = F17; F4 = F18; F5 = F19; F6 = F20; F7 = F21

Fig. 14



F1V = F22; F2V = F23; F1S = F24; F2S = F25; F3S = F26; F4S = F27

Fig. 15




Fig. 16




Fig. 16 continued

C







Fig. 17


Fig. 17 continued

C



F1V = F22; F2V = F23; F1S = F24; F2S = F25; F3S = F26; F4S = F27

D



F1V = F22; F2V = F23; F1S = F24; F2S = F25; F3S = F26; F4S = F27