

Method for removing residual monomers from polyoxymethylenes

Abstract

- 5 Process for removing unconverted residual monomers from polyoxymethylenes, wherein a devolatilization step is carried out in an extrudate devolatilizer.