

FIG. 1




FIG. 2




FIG. 3A




FIG. 3B




FIG. 4




FIG. 5




FIG. 6




FIG. 7






FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16




FIG. 18

A detailed cross-sectional view of a mechanical assembly. The assembly consists of two main components, 1 and 2, which are joined together. Component 1 is shown on the right, featuring a central bore with a shoulder 3a and a recessed area 3. Component 2 is shown on the left, with a corresponding shoulder 20 and a recessed area 2. A bolt 6 passes through both components, secured by washers 5 and 51. A seal or gasket 10B is located between the components. Various other parts are labeled with numbers: 1a, 1c, 1b, 15, 21, 25, 3, 5, 17, 19, 24, and K. Arrows Q indicate specific forces or directions.



FIG. 21

