DRY REACTIVE ION ETCHING

ABSTRACT

A method of etching a wafer includes the steps of applying a dry film resist to a surface to be etched, curing the dry film resist, patterning the dry film resist to expose areas of the wafer to be etched, etching the wafer with a dry reactive ion etch and removing the remaining dry film resist.

Figure 5