




FIG. 1




FIG. 2A




FIG. 2B




FIG. 2C




FIG. 3A





FIG. 3B






FIG. 3D

9/89

SQUARE HOLE ON RIGHT
BEND IN CORRECT DIRECTION




FIG. 4A




FIG. 4B




FIG. 4C




FIG. 4D




FIG. 4E




FIG. 5A




FIG. 5C

FIG. 5B





FIG. 5D



FIG. 5E



HOLE A: 4 PLACES, 0.26" DIA
HOLE B: 8 PLACES, CS FOR 8-32 FLAT HEAD SCREW, ON OUTSIDE SURFACE
HOLE C: 2 PLACES, 0.18" DIA

FIG. 5F




FIG. 6A




FIG. 6B




FIG. 6C



FIG. 6D





FIG. 7A



FLAT PATTERN
FIG. 7B



FIG. 7D




FIG. 7C




FIG. 8A




FIG. 8B




FIG. 8C




FIG. 8D




FIG. 9A




FIG. 9B





FIG. 9C



FIG. 9D



AREA SHOWN IN DARK GRAY
SHALL BE BLACK.

AREAS SHOWN IN LIGHT GRAY
SHALL BE TRANSPARENT.




FIG. 10D




FIG. 11A




FIG. 11B




FIG. 11C



FIG. 11D




FIG. 11E




FIG. 11F




FIG. 12A




FIG. 12B




FIG. 12C



FIG. 12D





FIG. 12E



HOLE A: 4 PLACES, 8-32 EXTRUDED AND TAPPED HOLES
HOLE B: 4 PLACES, HOLE FOR M6 PEM NUT

FIG. 12F




FIG. 13A




FIG. 13B





FIG. 14A







FIG. 15A






FIG. 16A




FIG. 16B





FIG. 16C



HOLE A: 2 PLACES, 8-32 EXTRUDED AND TAPPED

FIG. 16D




FIG. 16E





FIG. 17A



FLAT PATTERN
FIG. 17C




FIG. 17B




FIG. 17E



FIG. 17D




FIG. 18




FIG. 19




FIG. 20




FIG. 21




FIG. 22




FIG. 23A




FIG. 23B




FIG. 24A




FIG. 24B




FIG. 24C




FIG. 25




FIG. 26A




FIG. 26B

57/89




FIG. 26C




FIG. 27




FIG. 28A




FIG. 28B



FIG. 28C



FIG. 28D



FIG. 28E



FIG. 28F




FIG. 29A



FIG. 29B




FIG. 29C




FIG. 30A



FIG. 30B



FIG. 30C




FIG. 31A




FIG. 31B




FIG. 31C




FIG. 31D




FIG. 31E




FIG. 31F




FIG. 31G




FIG. 31H




FIG. 31I




FIG. 31J




FIG. 31K




FIG. 31L



FIG. 31M




FIG. 32A




FIG. 32B



FIG. 32C



FIG. 33A




FIG. 33B




FIG. 33C