




[Fig. 1A]




[Fig. 1B]




[Fig. 1C]




[Fig. 1D]



[Fig. 1E]



[Fig. 1F]




[Fig. 2A]

$$(X_0 \ X_1 \ X_2 \ X_3 \ \cdots \ X_{a-1})$$


$$\times$$

$$\begin{bmatrix} W_{00} & W_{01} & W_{02} & W_{03} & \cdots & W_{0(b-1)} \\ W_{10} & W_{11} & W_{12} & W_{13} & \cdots & W_{1(b-1)} \\ W_{20} & W_{21} & W_{22} & W_{23} & \cdots & W_{2(b-1)} \\ W_{30} & W_{31} & W_{32} & W_{33} & \cdots & W_{3(b-1)} \\ \vdots & \vdots & \vdots & \vdots & & \vdots \\ W_{a0} & W_{a1} & W_{a2} & W_{a3} & \cdots & W_{a(b-1)} \end{bmatrix}$$


[Fig. 2B]




[Fig. 2C]




[Fig. 2D]




[Fig. 2E]




[Fig. 2F]




[Fig. 3A]



[Fig. 4]



[Fig. 5]



[Fig. 6]

600