

Step 1: Surface Pre-clean



Step 2: Metal Passivation



Step 3: DoD Selective Dep




FIG. 1

2 / 5




FIG. 2

3/5




FIG. 3




FIG. 4

5 / 5




FIG. 5