

METHOD OF MANUFACTURING AN ACCELEROMETER

ABSTRACT

5

A method for manufacturing an accelerometer that includes the steps of etching at least one cavity into the top side of a substrate, bonding a top layer of material onto the top side of the substrate, depositing metallization onto the layer of material and etching to top layer of material to form a sensor structure suspended over each cavity.

10

Figure 11