




1/10

**FIGURE 1**


2/10

**FIGURE 2**


3/10

**FIGURE 3**

4/10

**FIGURE 4**


5/10




- 1) Heat from -50.00 °C to 170.00 °C at 10.00 °C/min
- 2) Cool from 170.00 °C to -50.00 °C at 200.00 °C/min
- 3) Hold for 8.0 min at -50.00 °C
- 4) Heat from -50.00 °C to 210.00 °C at 10.00 °C/min

FIGURE 5


6/10

**FIGURE 6**


7/10

**FIGURE 7**

8/10

**FIGURE 8**

9/10

**FIGURE 9**




FIGURE 10