

ABSTRACT

VACUUM DEPOSITION METHOD

5 A method of forming a layer on a substrate surface by vacuum deposition of particles onto the substrate surface, the method comprising the step of moving at least part of the substrate at high speed during vacuum deposition in a first direction parallel to the substrate surface.

10 (Figure 2)