




FIG. 1

200




FIG. 2




FIG. 3




FIG. 4A




FIG. 4B

500A

?

X

Mark as Actioned

Airplane: A360

Alert 00-1111-A321 MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure diffe...

504

Work Order *

AMM Tasks:

Fuel Filter Element - Removal - A787-A-123-44-12-34A-111A-A

Fuel Filter Element - Installation - A787-A-123-44-12-34A-222A-A

Main Fuel Pump Strainer - Removal - A787-A-123-44-12-34A-333A-A

Main Fuel Pump Strainer - Cleaning - A787-A-123-44-12-34A-444A-A

Main Fuel Pump Strainer - Inspection - A787-A-123-44-12-34A-555A-A

Main Fuel Pump Strainer - Installation - A787-A-123-44-12-34A-666A-A

502

Additional Comments

CANCEL

SAVE

FIG. 5A

500B

Update

Airplane: A360

Alert 00-1111-A321 MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure diffe...

504

Work Order*
AB1221

506

☒ Work Orders Closed

Additional Comments

All AMMs Completed YVR Station (M.Nichols). Waiting for readings to return below threshold at the end of the next leg for confirmation before resolving.

AMM Tasks:

Fuel Filter Element - Removal - A787-A-123-44-12-34A-111A-A

Fuel Filter Element - Installation - A787-A-123-44-12-34A-222A-A

Main Fuel Pump Strainer - Removal - A787-A-123-44-12-34A-333A-A

Main Fuel Pump Strainer - Cleaning - A787-A-123-44-12-34A-444A-A

Main Fuel Pump Strainer - Inspection - A787-A-123-44-12-34A-555A-A

Main Fuel Pump Strainer - Installation - A787-A-123-44-12-34A-666A-A

502

CANCEL

SAVE

FIG. 5B

500C

?

X

Mark as Resolved

Airplane: A360

Alert 00-1111-A321 MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure diffe...

504

Work Order*

AB1221

506

AMM Tasks:

Fuel Filter Element - Removal - A787-A-123-44-12-34A-111A-A

Fuel Filter Element - Installation - A787-A-123-44-12-34A-222A-A

Main Fuel Pump Strainer - Removal - A787-A-123-44-12-34A-333A-A

Main Fuel Pump Strainer - Cleaning - A787-A-123-44-12-34A-444A-A

Main Fuel Pump Strainer - Inspection - A787-A-123-44-12-34A-555A-A

Main Fuel Pump Strainer - Installation - A787-A-123-44-12-34A-666A-A

502

☒ Work Orders Closed *

☒ Condition Resolved *

508

Additional Comments

The alert has not been present in the last leg. Fuel pressure reading confirmed.

CANCEL

SAVE

FIG. 5C

500D

?

X

Mark for Rework

Airplane: A360

Item will be moved to the New Alerts queue. Original compliance window will be maintained.

Alert 00-1111-A321 MRBR AHM Task - Left fuel filter pressure drop exceeds MRBR limit - The measured pressure differe...

Work Orders	Work Order	Status	Condition
AZ123	Closed		Unresolved

Additional Comments

Fuel pressure continues to drop after maintenance. Sending item back for new work order.

CANCEL

SAVE

FIG. 5D

600

ML

Model
787

Airplane

Code or Description

Work Order

187 of 328 Airplanes

1001

History

Code

Description

Airplane	Model	Flight	Airports	0001	History	Code	Description	Compliance Window	Remaining	Compliance Status	Work Order
A109	787	058	AMS→YYR	On 16:46			MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure differential for the Right fuel filter exceeds the MRBR I		48 of 80 Flight Hours		AZ122
A457	787	058	AMS→YYR	On 16:46			MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure differential for the Right fuel filter exceeds the MRBR I		48 of 80 Flight Hours		AZ122
A376	787	578	CTS→TPE	On 16:46			MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure differential for the Right fuel filter exceeds the MRBR I		58 of 60 Flight Hours		AZ122

TO FIG. 6B

FIG. 6A

FROM FIG. 6A




A579	787	578	CTS→TPE		On 16:46		12-1111- ●●● -2 -1 0	A123	MRBR AHM Task - Right fuel filter pressure drop exceeds MRBR limit - The measured pressure differential for the Right fuel filter exceeds the MRBR I		58 of 60 Flight Hours		Needs Validation	AZ122
A009	787	241	CDG→YVR		In 16:42		00-1212- ○●● -2 -1 0	NoReport	MRBR AHM Task - NO Brake Servicing Information Report 710 received on this flight		33 of 40 Flight Cycles		Needs Validation	AZ1331
A012	787	241	CDG→YVR		In 16:42		00-1212- ○●● -2 -1 0	NoReport	MRBR AHM Task - NO Brake Servicing Information Report 710 received on this flight		33 of 40 Flight Cycles		Needs Validation	AZ1331
A420	787	241	DEN→SEA		In 12:51		00-1212- ○●● -2 -1 0	NoReport	MRBR AHM Task - NO Brake Servicing Information Report 710 received on this flight		16 of 40 Flight Cycles		Pending work	AZ1331
A312	787	578	SFO→MIA		In 08:08		44-5566- ○●● -2 -1 0	B123	MRBR AHM Task - Main Landing Gear Brake 8 percent remaining exceeds MRBR limit.		41 of 80 Flight Hours		Pending work	AZ1345
A215	787	240	LHR→YVR		In 12:51		13-0001- ○●● -2 -1 0	B012	MRBR AHM Task - Left fuel filter pressure drop exceeds MRBR limit - The measured pressure differential for the Left fuel filter exceeds the MRBR I		42 of 80 Flight Hours		Pending work	AZ5678

FIG. 6B

 600

700

Back

?

X

Scheduled Maintenance Alert Detail

708

☐ Needs action
Workflow Status: New

Alert Context

Airplane	Model	Flight Leg	Update Date	Depart	Arrive
A420	787	241 -0	24-Oct 12:51	In 12:51 NRT	SEA

Message History

Alert 00-1212-NoReport MRBR AHM Task - NO Brake Servicing Information Report 710 received on this flight

-9 -8 -7 -6 -5 -4 -3 -2 -1 0

☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ ☒

Alert 00-1212-NoReport MRBR AHM Task - NO Brake Servicing Information Report 710 received on this flight

Airplane	Model	ATA	Occurrence Date	Compliance Window	Remaining Units
A420	787	32	24-Oct-2023		29 of 40 Flight Hours remaining

Report History

Leg	Report
☐ ☒ ☒ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☐ ☒ ☒	-19 -18 -17 -16 -15 -14 -13 -12 -11 -10 -9 -8 -7 -6 -5 -4 -3 -2 -1 0

702

Related Documents

Aircraft Maintenance Manual
No Report Procedure

No Brake Servicing Report Procedure

Compliance Tasks

Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 1]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 2]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 3]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 4]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 5]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 6]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 7]
Brake Wear - Visual Check - B121-A-11-22-33-123-100A-C [MLG Brake 8]

704

Activity (1)

ML

Write a comment...

☒ Alert 24-Oct 12:51 MRBR AHM Task - NO Brake Servicing Information Report 710 received on this flight

706

FIG. 7




FIG. 8

ML

3

Fleet Data Health

902

< Reason Unknown (3)

ACARS MEL (5)

Other (3)

Model Last Transmission

A636 787 25-Oct-2023 08:16 (29 hrs ago)

Assign reason for data outage.

Model Last Transmission

A412 787 25-Oct-2023 09:21 (28 hrs ago)

Assign reason for data outage.

Model Last Transmission

A044 787 25-Oct-2023 11:06 (26 hrs ago)

Assign reason for data outage.

Model Last Transmission

A024 787 24-Oct-2023 08:33 (53 hrs ago)

Verification needed. 5 hrs overdue.

Model Last Transmission

A233 787 26-Oct-2023 11:18 (2 hrs ago)

Data received. Review scheduled maintenance.

Model Last Transmission

A050 787 24-Oct-2023 20:09 (41 hrs ago)

15 hrs until next verification.

Model Last Transmission

A007 787 25-Oct-2023 04:21 (33 hrs ago)

17 hrs until next verification.

Model Last Transmission

A564 787 25-Oct-2023 11:16 (26 hrs ago)

21 hrs until next verification.

Model Last Transmission

A478 787 25-Oct-2023 02:11 (35 hrs ago)

4 hrs until next verification.

Model Last Transmission

A645 787 25-Oct-2023 09:05 (28 hrs ago)

9 hrs until next verification.

Model Last Transmission

A301 787 25-Oct-2023 11:01 (26 hrs ago)

15 hrs until next verification.

1000A

Back

Airplane Data Health

Data Outage Reason: | Unknown ▾

Assign reason for data outage

Airplane Model Last Transmission

A636 787 25-Oct-2023 08:16 (29 hrs ago)

Data Outages - Last 90 Days

1004

13-Jul20-Jul27-Jul3-Aug10-Aug17-Aug24-Aug31-Aug7-Sep14-Sep21-Sep28-Sep5-Oct12-Oct19-Oct26-Oct

Enrolled Maintenance Tasks

Tire Pressure

Compliance Window: 12 Hours

▾

Fuel Filter - Left

Compliance Window: 80 Flight Hours

▾

Fuel Filter - Right

Compliance Window: 80 Flight Hours

▾

Brakes

Compliance Window: 40 Flight Cycles

▾

1002A

1006

FIG. 10A

16/37




FIG. 10B

1100 ↗

Assign Reason for Data Outage

⚠

Verification will be required every 24 hours for ACARS MEL outage

Airplane Model Last Transmission MEL Reference

A636 787 24-Oct-2023 07:21 (29 hrs ago) 11-22-33 1110

Reason * ACARS MEL ▼ 1102

MEL Log Page * 0001234 1104

ADD WORK ORDERS ▼

Tires

Compliance Window: 12 Hours

Work Orders: AX15767	1106
AMM Task	Tire Position
Landing Gear Tire - Pressure Test - B121-A-11-22-33-001B-123A-A	MLG Tire 1
Landing Gear Tire - Pressure Test - B121-A-11-22-33-001B-123A-A	MLG Tire 2
Landing Gear Tire - Pressure Test - B121-A-11-22-33-001B-123A-A	MLG Tire 3
Landing Gear Tire - Pressure Test - B121-A-11-22-33-001B-123A-A	MLG Tire 4

CANCEL

SAVE

FIG. 11

1000B

Back

Airplane Data Health

1000B

ACARS MEL

5 hours until next verification

1204

Last Transmission

25-Oct-2023 08:16 (29 hrs ago)

787

A636

1204

Last Updated

26-Oct-2023 13:03

Mike Lee

1204

MEL Log Page

0001234

1204

MEL Reference

11-22-33

1210

Update

Resolve

1002B

1206

25 Oct 2023 - 26 Oct 2023

ACARS MEL

14-Jul

21-Jul

28-Jul

4-Aug

11-Aug

18-Aug

25-Aug

1-Sep

8-Sep

15-Sep

22-Sep

29-Sep

6-Oct

13-Oct

20-Oct

27-Oct

Enrolled Maintenance Tasks

Tire Pressure

Compliance Window: 12 Hours

Work Orders: AZ00001

Fuel Filter - Left

Compliance Window: 80 Flight Hours

Work Orders: AZ00002, AZ00003

Fuel Filter - Right

Compliance Window: 80 Flight Hours

Work Orders: AZ00004, AZ00005

Brakes

Compliance Window: 40 Flight Cycles

Work Orders: AZ00006

Activity (1)

ML

Write a comment...

ML

Mike Lee

26-Oct 13:03

DATA HEALTH STATUS:

ACARS MEL

MEL LOG PAGE:

0001234

WORK ORDERS:

AZ00001

AZ00002

AZ00003

AZ00004

AZ00005

AZ00006

ADDITIONAL COMMENTS:

Confirmed that ACARS reports are unavailable. Added MEL...

Show more

1208

FIG. 12

19/37

1300

Update

ⓘ

Verification timer will be reset for 24 hours.

Airplane

Model

Last Transmission

Last Updated

Updated By

MEL Reference

A636

787

24-Oct-2023 10:21 (51 hrs ago)

25-Oct-2023 09:47

Mike Lee

11-22-33

Reason *

ACARS MEL

▼

*MEL Log Page

0001234

☒

Update verification status

EDIT WORK ORDERS

>

Additional Comments *

Verified missing ACARS. MEL Log Page status is still open.

CANCEL

SAVE

1306

1302

1304

FIG. 13

20/37

1500

Resolve

Outage Reason	Airplane	Model	Last Transmission	Last Updated	Updated By
ACARS MEL	A636	787	27-Oct-2023 08:09 (23 min ago)	27-Oct-2023 07:11	Mike Lee

MEL Log Page

MEL Reference

0001234

11-22-33

1502

Confirm All:

☒ MEL Resolved *

☒ Work Orders Completed/Canceled *

AZ00001

1504

AZ00002

AZ00003

AZ00004

AZ00005

AZ00006

Additional Comments *

All Work Orders have been completed or cancelled. Compliance windows verified.

1506

CANCEL

SAVE

FIG. 15

1600

Assign Reason for Data Outage

Verification will be required every 30 days when Exit Date is later than 30 days.

Airplane Model Last Transmission

A206 787 24-Oct-2023 07:21 (29 hrs ago)

1606

Reason * Maintenance Check

1602

Estimated Exit Date *

21-Dec-2023

1604

Additional Comments

Mx Check is estimated for 8 weeks due to availability of parts and labor. Station has been contracted.

CANCEL

SAVE

FIG. 16

FIG. 17

1000E

Back

Airplane Data Health

?

✕

Activity (1)

ML

Write a comment...

ML

Mike Lee

24-Oct 13:03

DATA HEALTH STATUS:

Maintenance Check

EST. EXIT DATE:

21-Dec-2023

ADDITIONAL COMMENTS:

Mx Check is estimated for 8 weeks due to availability of p...

Show more

30 days since last verification

1210

Update

Resolve

Airplane	Model	Last Transmission	1804	Est. Exit Date	Last Updated	Updated By
A206	787	25-Oct-2023 08:16 (31 days ago)	21-Dec-2023	27-Oct-2023 07:11	Mike Lee	

Data Outages - Last 90 Days

25 Oct 2023 - 26 Oct 2023

Maintenance Check

13-Aug

20-Aug

27-Aug

3-Sep

10-Sep

17-Sep

24-Sep

31-Sep

7-Oct

14-Oct

21-Oct

28-Oct

5-Nov

12-Nov

19-Nov

26-Nov

Enrolled Maintenance Tasks

Tire Pressure	Compliance Window: 12 Hours
Fuel Filter - Left	Compliance Window: 80 Flight Hours
Fuel Filter - Right	Compliance Window: 80 Flight Hours
Brakes	Compliance Window: 40 Flight Cycles

FIG. 18

1900

Update

Airplane	Model	Last Transmission	Last Updated	Updated By
A206	787	25-Oct-2023 08:16 (31 days ago)	27-Oct-2023 07:11	Mike Lee

Reason *
Maintenance Check

Estimated Exit Date *
21-Dec-2023

☒ Update verification status

Additional Comments
Still on track to complete work by 21-Dec-2023

CANCEL

SAVE

FIG. 19

900

Fleet Data Health			
ML			
< ACARS MEL (4)		Other (2)	
Model Last Transmission A233 787 25-Nov-2023 07:41 (2 hrs ago) Data received. Review scheduled maintenance.	Model Last Transmission A645 787 23-Nov-2023 19:46 (38 hrs ago) Verify status. 2 hrs overdue.	Model Last Transmission A212 787 22-Nov-2023 09:55 (78 hrs ago) Verify status. 3 hrs overdue.	
		Model Last Transmission A004 787 23-Nov-2023 14:35 (43 hrs ago) 8 hrs until next verification.	
		Model Last Transmission A478 787 23-Nov-2023 22:11 (35 hrs ago) 4 hrs until next verification.	
		Model Last Transmission A251 787 24-Nov-2023 02:22 (31 hrs ago) 16 hrs until next verification.	
Model Last Transmission A636 787 22-Nov-2023 19:27 (62 hrs ago) 5 hrs until next verification.	Model Last Transmission A443 787 24-Nov-2023 07:11 (26 hrs ago) 15 hrs until next verification.	Model Last Transmission A614 787 24-Nov-2023 07:11 (26 hrs ago) 21 hrs until next verification.	
Model Last Transmission A050 787 23-Nov-2023 08:22 (49 hrs ago) 5 hrs until next verification.	Model Last Transmission A007 787 24-Nov-2023 00:41 (33 hrs ago) 17 hrs until next verification.		

FIG. 20A

900

FIG. 20B

2200 ↗

Assign Reason for Data Outage

① Verification will be required every 24 hours

Airplane

Model

Last Transmission

A636

787

24-Oct-2023 07:21 (29 hrs ago)

Reason *

Other

2202

2204

ADD WORK ORDERS >

Additional Comments *

The plane is still in service, but it was determined that the loss of connectivity is not an ACARS MEL situation.

2206

CANCEL

SAVE

FIG. 22

FIG. 23

FIG. 23

2400

Update

Airplane	Model	Last Transmission	Last Updated	Updated By
A206	787	25-Oct-2023 08:16 (31 days ago)	27-Oct-2023 07:11	Mike Lee

Reason *

Other

☐ Update verification status

EDIT WORK ORDERS >

Additional Comments

2402

2404

CANCEL

SAVE

FIG. 24

2500

Assign Reason for Data Outage

Verification will be required every 24 hours

Airplane	Model	Last Transmission
A636	787	24-Oct-2023 07:21 (29 hrs ago)

Reason *

Out of Service

Additional Comments *

CANCEL

SAVE

FIG. 25

33/37

1000G

Back

Airplane Data Health

Activity (1)

ML Write a comment...

ML Mike Lee

26-Oct 13:03

DATA HEALTH STATUS:

Out of Service

ADDITIONAL COMMENTS:

Plane is currently parked because of unexpected issue...

Show more

2608

24 hours until next verification.

Airplane Model

Last Transmission

2604

Last Updated

26-Oct-2023 13:03

Mike Lee

Updated By

1002E

A636

787

25-Oct-2023 08:16 (29 hrs ago)

Data Outages - Last 90 Days

25 Oct 2023 -

26 Oct 2023

ACARS MEL

13-Jul

20-Jul

27-Jul

3-Aug

10-Aug

17-Aug

24-Aug

31-Aug

7-Sep

14-Sep

21-Sep

28-Sep

5-Oct

12-Oct

19-Oct

26-Oct

Enrolled Maintenance Tasks

Tire Pressure	Compliance Window: 12 Hours	Work Orders: AZ00001	>
Fuel Filter - Left	Compliance Window: 80 Flight Hours	Work Orders: AZ00002, AZ00003	>
Fuel Filter - Right	Compliance Window: 80 Flight Hours	Work Orders: AZ00004, AZ00005	>
Brakes	Compliance Window: 40 Flight Cycles	Work Orders: AZ00006	>

2606

FIG. 26

2700

Update

Airplane	Model	Last Transmission	Last Updated	Updated By
212	787	24-Oct-2023 10:21 (51 hrs ago)	25-Oct-2023 09:47	Mike Lee

*Reason
Out of Service

☐ Update verification time

EDIT WORK ORDERS >

*Additional Comments

2702

2704

CANCEL

SAVE

FIG. 27




FIG. 28




FIG. 29




FIG. 30