




FIG. 1A




FIG. 1B




FIG. 2

2/14




FIG.3A




FIG.3B






FIG.3C

**FIG.4****FIG.5**

4/14




FIG. 6A




FIG. 6B




FIG.7A




FIG.7B




FIG.8




FIG. 9A




FIG. 9B

7/14




FIG. 10A

$h_T = 0$




FIG. 10B

$h_T = h_M$




FIG. 10C

8/14




FIG.11




FIG.12

FIG.13A




FIG.13B





FIG.14






FIG.15A




FIG.15B





FIG.15C

**FIG.16**




FIG.17