162162

ABSTRACT

G00002

A METHOD TO FABRICATE RF INDUCTORS WITH MINIMUM AREA

A method for forming an RF inductor of helical shape having high Q and minimum area. The inductor is fabricated of metal or damascened linear segments formed on three levels of intermetal dielectric layers and interconnected by metal filled vias to form the complete helical shape with electrical continuity.

FIGURE 16