COMPOSITE FILLED METAL AIRFOIL

ABSTRACT

A method of forming an airfoil includes forming a metal portion of the airfoil including a tip, a leading edge, a trailing edge, a pressure side and a suction side; forming a plurality of grooves into one side of the airfoil; and filling the plurality of grooves with composite material.

Figure 2