




[図1]




[図2]




[図3A]



[図3B]



[図4]




[illegible]




The diagram illustrates a mechanical system, possibly a textile loom, with various components and their interconnections. The system includes a control panel (80) with buttons (83, 84) and a display (12). A complex arrangement of pulleys, belts, and rods (10, 10a, 10b, 14, 16, 20, 24a, 24b, 24c, 26a, 26b, 26c, 32, 33, 34, 36, 90, 91) is shown. A motor (E) is connected to the system. A force vector F is indicated. The diagram is labeled with numerous reference numerals.


[図8]



[図9]



[図10]



[図11]

