

X-Achse = X-axis
Y-Achse = Y-axis
Z-Achse = Z-axis





Fig.1




(1): Camera (optics) in the center of the first turning device directed at chip supply

(2): Camera (arrangement) having 1 - 3 cameras at the periphery of the first turning device directed at 90° at the chip

(3): Camera (arrangement) having 1 - 3 cameras at the periphery of the second turning device directed at 90° at the chip

(4): Camera (optics) in the center of the second turning device directed at receiving point(s) in the receiving device






Fig. 4

