

METHOD FOR MANUFACTURING INORGANIC SPHEROIDIZED PARTICLES

[ABSTRACT]

A method for producing inorganic spheroidized particles according to the present invention includes a step of producing the inorganic spheroidized particles by means of a diffusion type burner (12), wherein the burner (12) comprises a first raw
5 material supply path (1A), a fuel supply path (4A), a raw material diffusion chamber (9), a primary oxygen supply path (5A), a second raw material supply path (6A), a secondary oxygen supply path (7A), and a combustion chamber (8).

Fig. 1