

FIG. 1




FIG. 2




FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12A




FIG. 12B




FIG. 12C




FIG. 13A




FIG. 13B

0. 2mm




FIG. 13C

0. 3mm




FIG. 13D

0. 4mm




FIG. 13E




FIG. 14A

w/o




FIG. 14B

blanket




FIG. 14C

frame(ring)




FIG. 15




FIG. 16A




FIG. 16B




FIG. 17A

non (ref.)



FIG. 17B

0.1mm



FIG. 17C

0. 2mm




FIG. 17D

0. 3mm




FIG. 17E

0. 5mm




FIG. 18A





FIG. 18B



Sheet  
t=0.1 ~ 0.4mm

FIG. 19A

non (ref.)



FIG. 19B

0. 1mm




FIG. 19C

0. 2mm




FIG. 19D

0. 3mm




FIG. 19E

0. 4mm




FIG. 20




FIG. 21




FIG. 22




FIG. 23

