

FIG.1




FIG.2




FIG.3A




FIG.3B




FIG.3C




FIG.4A




FIG.4B




FIG.4C




FIG.5A




FIG.5B




FIG.5C




FIG.6A




FIG.6B




FIG.6C




FIG.7A




FIG.7B




FIG.7C




FIG.8A




FIG.8B




FIG.8C




FIG.9




FIG.10A




FIG.10B




FIG.10C




FIG.10D




FIG.10E




FIG.11A




FIG.11B






FIG.12A




$Q_u=33$

FIG.12B




$Q_u=64$

FIG.12C



$Q_u=68$

FIG.13








FIG.15






FIG. 16A





FIG. 16B

FIG.17



$$S=0.5\text{nm}^2$$