




FIG. 1


FIG. 1: curves σ - ϵ for stainless steel and carbon steel

FIG. 2




FIG. 3

FIG. 4 A




FIG. 4 B




FIG. 4 C




Fig. 5




FIG. 6




FIG. 7




FIG. 8




FIG. 9




FIG. 10




FIG. 11




FIG. 12





FIG. 13






FIG. 14

FIG. 14A