

Fig 1






FIG. 1 is a schematic diagram of a mechanical assembly 10, showing a top-down view of a central circular component 21. The assembly is housed within a rectangular frame 12. Key components include a central shaft 38, two side arms 16, and two side assemblies 22. Dimensions C1, C2, D1, and D2 are indicated. Labels 14, 18, 20, 24, 26, 32, 34, 40, 42, 44, 46, 60, 62, 64, 66, 68, 70, 72, and T are used to identify various parts and features.

Fig 4






Fig 6

