




[Fig. 1]




[Fig.2]




[Fig. 3]




[Fig. 4]



[Fig. 5a]




[Fig. 5b]




7/23


[Fig. 5c]


c




[Fig. 6]

[Fig. 7]




[Fig. 8]

[Fig. 9]




	Pure Buffer	Pure BSA-TTC
FM	2.46E+04	9.79E+05
Total Matrix	1406.876	307932

[Fig. 10]



[Fig. 11b]

b



[Fig. 12a]







Fig. 12b]




[Fig. 13]




[Fig. 14]




[Fig.15]



[Fig. 16]

[Fig. 17]



	P-001	P-002	P-003	P-004	P-005	P-006
n	850000	800000	750000	650000	850000	50000

[Fig. 18]